








$\varnothing 14$ 		38x15cm 	L=167cm 	$\varnothing 4.0 \times 30\text{mm}$ 	M5,8x30mm
E13 4	O 1	SX15 2	SS4 2	R2 12	U16 4

$\varnothing 8 \times 30\text{mm}$ 	$\varnothing 6 \times 42\text{mm}$ 	$\varnothing 15/12\text{mm}$ 	$\varnothing 12/10\text{mm}$ 	L=20mm 		$\varnothing 35/16\text{mm}$
A 32	B2 4	C 16	C5 4	D2 20	E 12	HG2 4

27/310mm 					$\varnothing 6,3 \times 13\text{mm}$ 	$\varnothing 10 \times 50\text{mm}$ 	$\varnothing 3.5 \times 13\text{mm}$ 	$\varnothing 3.0 \times 20\text{mm}$ 	M4x9mm
I4 2	K4 2	L 20	L9 1	L46 4	M2 8	O7 1	P5 29	P7 6	U1 4







OZM.103	433x399x16
OZM.104	433x399x16
OZM.503	417x358x16
OZM.504	417x358x16
OZM.201	1746x400x16
OZM.401	1712x381x16
OZM.901 x2	550x70x16
OZM.604	1721x426x2,5
OZM.603 x2	557x327x2,5
WST.0183 x2	330x100x12
WST.0184 x2	330x100x12
WST.0336 x2	546x100x12
OZM.701 x2	212x608x16
OZM.703 x2	372x546x18




1


±12/10mm  C5	±8x30mm  A
4	8





x2



2




±6x42mm  B2
4




x2

3



L=20mm  D2
4








x2





4





x2




5





















x2













6

$\pm 8 \times 30 \text{mm}$  A	$\pm 15/12 \text{mm}$  C	$L=20 \text{mm}$  D2	$27/310 \text{mm}$  I4	$\pm 6,3 \times 13 \text{mm}$  M2	 L46	$\pm 3.5 \times 13 \text{mm}$  P5
12	12	4	2	8	2	4







7


$\varnothing 8 \times 30 \text{mm}$  A	$\varnothing 15/12 \text{mm}$  C	L=20mm  D2	 L46	$\varnothing 3.5 \times 13 \text{mm}$  P5
12	4	12	2	4














8








9









$\pm 3.0 \times 20 \text{ mm}$  P7 6	 L 16
--	--



38x15cm  SX15 2	L=167cm  SS4 2	M5,8x30mm  U16 4	4.0x30mm  R2 12	 O 1	14  E13 4
---	--	--	---	---	---








 $\pm 10 \times 50 \text{ mm}$	 $\pm 3.5 \times 13 \text{ mm}$	 $\pm 3.5 \times 13 \text{ mm}$
O7	L9	P5
1	1	1




13





M4x9mm

U1
4



14

$\nabla 35/16\text{mm}$	$\nabla 3.5 \times 13\text{mm}$	
HG2	P5	K4
4	14	2



3.5x13mm  P5 6	 E 12
---	---

